



HEATCRAFT AUSTRALIA PTY LTD  
286 Horsley Road Milperra NSW 2214  
Locked Bag 6501 Regents Park NSW 2143  
Ph: 61 2 9774 7155 Fax: 61 2 9774 7205  
A.B.N. 67 000 056 717

March 12, 2013

Dear Customer,

**Refrigerant Price Increase – Effective 15<sup>th</sup> April, 2013**

The ongoing tightening of the volume of HCFC products available to the marketplace and pressure on the price of these refrigerants, Heatcraft has recently been advised of significant increases in our costs of HCFC refrigerants, which prompts the need to increase our HCFC Refrigerant list prices.

**We advise that Heatcraft list prices for the following HCFC refrigerants will increase as shown below, effective 15<sup>th</sup> April 2013.**

Product		% Change
<b>R22</b>	R22 REFRIGERANT	26%
<b>R409A</b>	R409A REFRIGERANT	20%
<b>R406A</b>	R406A REFRIGERANT	20%
<b>R123</b>	R123 REFRIGERANT	21%

Heatcraft offers a range of HFC-based refrigerants which can replace R22 in many systems such as R438A (ISCEON<sup>®</sup> MO99<sup>™</sup>), R407F, and R407C.

At Heatcraft we remain committed to providing customers value through Gas2Go<sup>®</sup> Australia's leading refrigerant management system, contact us now about Heatcraft Gas2Go<sup>®</sup> Club and club membership benefits.

Should you have any questions regarding the refrigerant increase, the alternative refrigerant and equipment options, please contact your local Heatcraft representative, or myself directly on (02) 9774 7070.

Yours sincerely,

Leon Miller  
Director of Sales